Montana Board of Oil and Gas Conservation Environmental Assessment

Well Name/Number: _Westbrook 1-22H
Location: SE SW Section 22 T27N R56E
County: Richland , MT; Field (or Wildcat) W/C (Bakken Formation Horizontal)
· · · · · · · · · · · · · · · · · · ·
Air Quality
(possible concerns)
Long drilling time: No, 30 to 40 days drilling time.
Unusually deep drilling (high horsepower rig): No, triple derrick drilling rig to drill a single
lateral Bakken formation horizontal well, 19,251'MD/9,191'TVD.
Possible H2S gas production: Slight chance H2S gas production.
In/near Class I air quality area: No Class I air quality area.
Air quality permit for flaring/venting (if productive): Yes, DEQ air quality permit required
under 75-2-211
Mitigation:
X Air quality permit (AQB review)
Gas plants/pipelines available for sour gas
Special equipment/procedures requirements
Other:
Comments: No special concerns – using triple derrick rig to drill a single lateral
Bakken formation horizontal well, 19,251'MD/9,191'TVD. If there are existing pipeline
for gas in the area then gas must be tied into system or if no gathering system nearby
gas can be flared under Board Rule 36.22.1220.
940 5411 25 11410 4 41140 1 50141 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Water Quality
(possible concerns)
(possible concerns) Salt/oil based mud: Yes, freshwater and freshwater mud system on surface hole, oil
(possible concerns) Salt/oil based mud: Yes, freshwater and freshwater mud system on surface hole, oil based invert mud system on mainhole and saltwater for the horizontal lateral hole.
(possible concerns) Salt/oil based mud: Yes, freshwater and freshwater mud system on surface hole, oil based invert mud system on mainhole and saltwater for the horizontal lateral hole. High water table: None anticipated, in the area of review.
(possible concerns) Salt/oil based mud: Yes, freshwater and freshwater mud system on surface hole, oil based invert mud system on mainhole and saltwater for the horizontal lateral hole. High water table: None anticipated, in the area of review. Surface drainage leads to live water: No, closest drainage is an unnamed ephemeral
(possible concerns) Salt/oil based mud: Yes, freshwater and freshwater mud system on surface hole, oil based invert mud system on mainhole and saltwater for the horizontal lateral hole. High water table: None anticipated, in the area of review. Surface drainage leads to live water: No, closest drainage is an unnamed ephemeral tributary drainage to Day Creek, adjacent to the northeast edge of the location. The
(possible concerns) Salt/oil based mud: Yes, freshwater and freshwater mud system on surface hole, oil based invert mud system on mainhole and saltwater for the horizontal lateral hole. High water table: None anticipated, in the area of review. Surface drainage leads to live water: No, closest drainage is an unnamed ephemeral tributary drainage to Day Creek, adjacent to the northeast edge of the location. The Missouri River is about 3 miles to the north from this location.
(possible concerns) Salt/oil based mud: Yes, freshwater and freshwater mud system on surface hole, oil based invert mud system on mainhole and saltwater for the horizontal lateral hole. High water table: None anticipated, in the area of review. Surface drainage leads to live water: No, closest drainage is an unnamed ephemeral tributary drainage to Day Creek, adjacent to the northeast edge of the location. The Missouri River is about 3 miles to the north from this location. Water well contamination: No, closest water wells nearby are about ¼ of a mile to the
(possible concerns) Salt/oil based mud: Yes, freshwater and freshwater mud system on surface hole, oil based invert mud system on mainhole and saltwater for the horizontal lateral hole. High water table: None anticipated, in the area of review. Surface drainage leads to live water: No, closest drainage is an unnamed ephemeral tributary drainage to Day Creek, adjacent to the northeast edge of the location. The Missouri River is about 3 miles to the north from this location. Water well contamination: No, closest water wells nearby are about ¼ of a mile to the east, about 3/8 of a mile to the north, about ½ of a mile to the east and ¾ of a miless to
(possible concerns) Salt/oil based mud: Yes, freshwater and freshwater mud system on surface hole, oil based invert mud system on mainhole and saltwater for the horizontal lateral hole. High water table: None anticipated, in the area of review. Surface drainage leads to live water: No, closest drainage is an unnamed ephemeral tributary drainage to Day Creek, adjacent to the northeast edge of the location. The Missouri River is about 3 miles to the north from this location. Water well contamination: No, closest water wells nearby are about ¼ of a mile to the east, about 3/8 of a mile to the north, about ½ of a mile to the east and ¾ of a miless to the north from this location. Domestic and stock water well depths range from 65' to
(possible concerns) Salt/oil based mud: Yes, freshwater and freshwater mud system on surface hole, oil based invert mud system on mainhole and saltwater for the horizontal lateral hole. High water table: None anticipated, in the area of review. Surface drainage leads to live water: No, closest drainage is an unnamed ephemeral tributary drainage to Day Creek, adjacent to the northeast edge of the location. The Missouri River is about 3 miles to the north from this location. Water well contamination: No, closest water wells nearby are about ¼ of a mile to the east, about 3/8 of a mile to the north, about ½ of a mile to the east and ¾ of a miless to the north from this location. Domestic and stock water well depths range from 65' to 200'. Surface casing will be drilled with freshwater, steel casing will be set and cement
(possible concerns) Salt/oil based mud: Yes, freshwater and freshwater mud system on surface hole, oil based invert mud system on mainhole and saltwater for the horizontal lateral hole. High water table: None anticipated, in the area of review. Surface drainage leads to live water: No, closest drainage is an unnamed ephemeral tributary drainage to Day Creek, adjacent to the northeast edge of the location. The Missouri River is about 3 miles to the north from this location. Water well contamination: No, closest water wells nearby are about ¼ of a mile to the east, about 3/8 of a mile to the north, about ½ of a mile to the east and ¾ of a miless to the north from this location. Domestic and stock water well depths range from 65' to 200'. Surface casing will be drilled with freshwater, steel casing will be set and cement to surface from 975'.
(possible concerns) Salt/oil based mud: Yes, freshwater and freshwater mud system on surface hole, oil based invert mud system on mainhole and saltwater for the horizontal lateral hole. High water table: None anticipated, in the area of review. Surface drainage leads to live water: No, closest drainage is an unnamed ephemeral tributary drainage to Day Creek, adjacent to the northeast edge of the location. The Missouri River is about 3 miles to the north from this location. Water well contamination: No, closest water wells nearby are about ¼ of a mile to the east, about 3/8 of a mile to the north, about ½ of a mile to the east and ¾ of a miless to the north from this location. Domestic and stock water well depths range from 65' to 200'. Surface casing will be drilled with freshwater, steel casing will be set and cement to surface from 975'. Porous/permeable soils: No, sandy clay soils.
(possible concerns) Salt/oil based mud: Yes, freshwater and freshwater mud system on surface hole, oil based invert mud system on mainhole and saltwater for the horizontal lateral hole. High water table: None anticipated, in the area of review. Surface drainage leads to live water: No, closest drainage is an unnamed ephemeral tributary drainage to Day Creek, adjacent to the northeast edge of the location. The Missouri River is about 3 miles to the north from this location. Water well contamination: No, closest water wells nearby are about ¼ of a mile to the east, about 3/8 of a mile to the north, about ½ of a mile to the east and ¾ of a miless to the north from this location. Domestic and stock water well depths range from 65' to 200'. Surface casing will be drilled with freshwater, steel casing will be set and cement to surface from 975'. Porous/permeable soils: No, sandy clay soils. Class I stream drainage: Closest Class I stream drainages in the area of review is the
(possible concerns) Salt/oil based mud: Yes, freshwater and freshwater mud system on surface hole, oil based invert mud system on mainhole and saltwater for the horizontal lateral hole. High water table: None anticipated, in the area of review. Surface drainage leads to live water: No, closest drainage is an unnamed ephemeral tributary drainage to Day Creek, adjacent to the northeast edge of the location. The Missouri River is about 3 miles to the north from this location. Water well contamination: No, closest water wells nearby are about ¼ of a mile to the east, about 3/8 of a mile to the north, about ½ of a mile to the east and ¾ of a miless to the north from this location. Domestic and stock water well depths range from 65' to 200'. Surface casing will be drilled with freshwater, steel casing will be set and cement to surface from 975'. Porous/permeable soils: No, sandy clay soils. Class I stream drainage: Closest Class I stream drainages in the area of review is the Missouri River.
(possible concerns) Salt/oil based mud: Yes, freshwater and freshwater mud system on surface hole, oil based invert mud system on mainhole and saltwater for the horizontal lateral hole. High water table: None anticipated, in the area of review. Surface drainage leads to live water: No, closest drainage is an unnamed ephemeral tributary drainage to Day Creek, adjacent to the northeast edge of the location. The Missouri River is about 3 miles to the north from this location. Water well contamination: No, closest water wells nearby are about ¼ of a mile to the east, about 3/8 of a mile to the north, about ½ of a mile to the east and ¾ of a miless to the north from this location. Domestic and stock water well depths range from 65' to 200'. Surface casing will be drilled with freshwater, steel casing will be set and cement to surface from 975'. Porous/permeable soils: No, sandy clay soils. Class I stream drainage: Closest Class I stream drainages in the area of review is the Missouri River. Mitigation:
(possible concerns) Salt/oil based mud: Yes, freshwater and freshwater mud system on surface hole, oil based invert mud system on mainhole and saltwater for the horizontal lateral hole. High water table: None anticipated, in the area of review. Surface drainage leads to live water: No, closest drainage is an unnamed ephemeral tributary drainage to Day Creek, adjacent to the northeast edge of the location. The Missouri River is about 3 miles to the north from this location. Water well contamination: No, closest water wells nearby are about ¼ of a mile to the east, about 3/8 of a mile to the north, about ½ of a mile to the east and ¾ of a miless to the north from this location. Domestic and stock water well depths range from 65' to 200'. Surface casing will be drilled with freshwater, steel casing will be set and cement to surface from 975'. Porous/permeable soils: No, sandy clay soils. Class I stream drainage: Closest Class I stream drainages in the area of review is the Missouri River. Mitigation: Lined reserve pit
(possible concerns) Salt/oil based mud: Yes, freshwater and freshwater mud system on surface hole, oil based invert mud system on mainhole and saltwater for the horizontal lateral hole. High water table: None anticipated, in the area of review. Surface drainage leads to live water: No, closest drainage is an unnamed ephemeral tributary drainage to Day Creek, adjacent to the northeast edge of the location. The Missouri River is about 3 miles to the north from this location. Water well contamination: No, closest water wells nearby are about ¼ of a mile to the east, about 3/8 of a mile to the north, about ½ of a mile to the east and ¾ of a miless to the north from this location. Domestic and stock water well depths range from 65' to 200'. Surface casing will be drilled with freshwater, steel casing will be set and cement to surface from 975'. Porous/permeable soils: No, sandy clay soils. Class I stream drainage: Closest Class I stream drainages in the area of review is the Missouri River. Mitigation: Lined reserve pit X Adequate surface casing
(possible concerns) Salt/oil based mud: Yes, freshwater and freshwater mud system on surface hole, oil based invert mud system on mainhole and saltwater for the horizontal lateral hole. High water table: None anticipated, in the area of review. Surface drainage leads to live water: No, closest drainage is an unnamed ephemeral tributary drainage to Day Creek, adjacent to the northeast edge of the location. The Missouri River is about 3 miles to the north from this location. Water well contamination: No, closest water wells nearby are about ¼ of a mile to the east, about 3/8 of a mile to the north, about ½ of a mile to the east and ¾ of a miless to the north from this location. Domestic and stock water well depths range from 65' to 200'. Surface casing will be drilled with freshwater, steel casing will be set and cement to surface from 975'. Porous/permeable soils: No, sandy clay soils. Class I stream drainage: Closest Class I stream drainages in the area of review is the Missouri River. Mitigation: Lined reserve pit X Adequate surface casing Berms/dykes, re-routed drainage
(possible concerns) Salt/oil based mud: Yes, freshwater and freshwater mud system on surface hole, oil based invert mud system on mainhole and saltwater for the horizontal lateral hole. High water table: None anticipated, in the area of review. Surface drainage leads to live water: No, closest drainage is an unnamed ephemeral tributary drainage to Day Creek, adjacent to the northeast edge of the location. The Missouri River is about 3 miles to the north from this location. Water well contamination: No, closest water wells nearby are about ¼ of a mile to the east, about 3/8 of a mile to the north, about ½ of a mile to the east and ¾ of a miless to the north from this location. Domestic and stock water well depths range from 65' to 200'. Surface casing will be drilled with freshwater, steel casing will be set and cement to surface from 975'. Porous/permeable soils: No, sandy clay soils. Class I stream drainage: Closest Class I stream drainages in the area of review is the Missouri River. Mitigation: Lined reserve pit X Adequate surface casing

<u>pit.</u>
Comments:975' of surface casing cemented to surface adequate to protect
freshwater zones.
Soils/Vegetation/Land Use
(possible concerns)
Steam crossings: No, stream crossings anticipated. Crossing only ephemeral
drainages
High erosion potential: Yes possible high erosion from steep cuts and fills, moderate
cut, up to 34.2' and moderate fill, up to 23.0' required.
Loss of soil productivity: No, location will be restored after drilling, if nonproductive. If
productive unused portion of drillsite will be reclaimed
Unusually large wellsite: No. 500'X300' location size required.
Damage to improvements: No, surface use is grassland.
Conflict with existing land use/values: Slight
Mitigation
Avoid improvements (topographic tolerance)
Exception location requested
X Stockpile topsoil
Stream Crossing Permit (other agency review)
X Reclaim unused part of wellsite if productive
Special construction methods to enhance reclamation
Other
Comments: Will use existing State Highway, #16. About 421' of new access
road will be built into this location, off State Highway, #16. About 4,971' of new access
road will be built into this location. A closed loop mud system will be utilized in the
drilling of this well. Drill cutting will be disposed of in a lined cuttings pit on the well
location. Oil based drilling fluids will be recycled. Pit fluids will be recycled and/or haul to a commercial SWD disposal. Lined cuttings pit will be backfilled when dry. No special
concerns.
CONCENTS.
Health Hazards/Noise
(possible concerns)
Proximity to public facilities/residences: Closest residences are about ¼ of a mile to the
east from this location.
Possibility of H2S: Slight chance of H2S (Mississippian Formations).
Size of rig/length of drilling time: Triple drilling rig/short 30 to 40 days drilling time.
Mitigation:
_X_Proper BOP equipment
Topographic sound barriers
H2S contingency and/or evacuation plan
Special equipment/procedures requirements
Other:
Comments: Operational BOP and adequate surface casing will mitigate any
problems that may occurNo concerns

Wildlife/recreation

Remarks or Special Concerns for this site

Well is a single lateral Bakken formation horizontal well, 19,251'MD/9,191'TVD.

Summary: Evaluation of Impacts and Cumulative effects

No long term impact expected, some short term impacts will occur.

I conclude that the approval of the subject Notice of Intent to Drill (does/ <u>does not</u>) constitute a major action of state government significantly affecting the quality of the human environment, and (does/ <u>does not</u>) require the preparation of an environmental impact statement.
Prepared by (BOGC): <u>/s/Steven Sasaki</u> (title:) <u>Chief Field Inspector</u> Date: <u>March 9, 2012</u>
Other Persons Contacted:
_Montana Bureau of Mines and Geology, GWIC website
(Name and Agency) Richland County water wells
(subject discussed) March 9, 2012 (date)
US Fish and Wildlife, Region 6 website (Name and Agency) ENDANGERED, THREATENED, PROPOSED AND CANDIDATE SPECIES MONTANA COUNTIES, Richland County (subject discussed)
March 9, 2012 (date)
Montana Natural Heritage Program Website (FWP) (Name and Agency) Heritage State Rank= S1, S2, S3, T27N R56E (subject discussed)
March 9, 2012 (date)
If location was inspected before permit approval: Inspection date: Inspector: Others present during inspection: